	CLASSIFICATION	ON SECURITY IN	FORMATION	25V1	25X1/
COUNTRY	ost CApproved For Rele	ase 2002/07/15 : C	IA-RDP807008010	A000900520009-6	_
	charfheide Airfield				The second secon
:					
EVALUATION_	see helow	PLACE OBTAIN	ED		25X10
		9 February 1953			
DATE OF CON			25X1C PREPARED	18 March 1953	
DATE OBTAIN		25X1/			-
REFERENCES 3		The special property and		a letter (ocoy)	A CAMPAC AND A CAM
PAGES	ENCLOSURES (
REMARKS	Annex forwards	<u>d</u>	20/(1	Early with a second law or the second plant operation or the second second law as a few second secon	
			THE PERSON NAMED IN COLUMN TO PERSON WHEN THE		gent finite an account of the last section of
AUGUSTA TAL SALEMANNAN ORDER WAS A MAD JAMES TO	Annandrian Proposition (1997)				
	25>	X1X			annang kamal permisi an nyaga anyan ang ang ang ang ang ang ang ang ang a
THE PROPERTY LINE AND ADDRESS AND EXPERTY VALUE OF A STATE OF THE PROPERTY AND ADDRESS AND	open have reason to 1994, yearly to be an execution to reason advanced to the country in the country of the cou	Parameter Processed Development Control			
				0	
X1X 2. 4	ars used for the ships he code designation to be assembled into to coded freight cars can after 12 January, mate airfield. Every mornin logelsang station and freight cars observed material and special of this train would return	mains at lempton me from the Cot erial shipments ng 30 to 40 frei then dispatched included gondol cars as used for m and proceed t	arrived at an ght cars were about 8 a.m. a cars loaded the shipment coward Templin.	Halle and Erfurt increased rate at assembled into one to the construction with coal and come of cement and limit	Schorfheide e train at on site. The struction e. At 4 p.m.,
	In the second half of being built by a Bauge construction firm of (track was to be comple project the code word January, the line had originated at Vogelsa Grunewald and continu construction material entered the airfield	emeinschaft i in Guenther. Work v eted by 1 Februa "Vogel". The sp been constructions south of Bern ted as far as the s were shipped	was being done ary. The railr pur track is ted as far as k gluch, passed a wooded area on a narrow-ge	elso at night bed oed administration to be 13.5 km in less m marker 9.1. The along the southers east of Grunevald auge railroad track	cause the spur had given this ength. By 25 spur track perimeter of From there the the spur track a that it was to
	entered the airfield continue from that p There were trucks on round. Prior to 9 Feb track arrived. Source runway were to be shi The chief of the Sovi railroad officials reairfield. Two railroad railroad railroad officials reairfield.	area near km ma point toward the both sides of t pruery, mostly m legislating learned that m ipped to this fi iet transport co	east as far a he shed, making aterials used naterials required after 20 lentrol headquares	as a storage shed ing it possible for for the constructived for the constructived for the constructury. 2 rters made qualification of materials ships	300 meters long trains to turn ion of the spur ruction of the decrease and German oments to the
*	eirfield. Two railro	GEODEW /] 25X
	OLAGOR TOA	.,,,,,			

	Approved For Release 2002/07/15 : CIA-RDP8029000104000900520009-6
	SECRET/
	25X1A
	dispatch to the airfield of trains loaded with construction materials.
5.	In the second half of January, part of the construction materials were delivered
	from Leipzig. The gravel was supplied by local gravel pits. Some of the rails used for the construction of the spur track were welded together; 3 or 4
	different profiles were delivered. Source learned that according to Soviet
	orders 4x180-axle trains loaded with construction materials and car loads of gravel were to be shipped daily to the airfield after 1 February. This material
25X1X	was to be unloaded in the airfield area, where two unloading ramps were
	scheduled to be built.3
6.	
	of the airfield in the second half of January. Source obtained a memorandum of the Bau-Union Brandenburg which criticized the conduct of Scheddin and von
9	Roedern, two construction supervisors at the airfield who had to be discharged
	because of gross negligence of duty and drunkenness.
7	On 19 January 1953, Teutsch (fnu) the replacement of the previous construction
()	supervisor von Roedern arrived at the airfield. In early February, the Soviet engineer and air force soldiers previously employed on the construction site had
	left. Only the road blocks and gates were guarded by Soviet soldiers who,
	allegedly, were trucked to the field from Templin. In the second half of January, the progress of construction work at the field was delayed by unfavorable weather
	conditions. Source learned that new construction workers were not be recruited
	before 1 March.
8	On 4 February, a railroad commission which was to accept the spur track to the field
25X1X	determined that the foundation of the line was defective. In spite of this finding the completion of the line was celebrated on 6 February by the firms which had
25/1/	participated in its construction.
9	In early February, source determined that the sour track to the airfield branched
	off toward the southeast from the Zehdenick-Templin railroad line at km marker
	14.3. The spur track crossed the Zehdenick-Templin highway between km markers 15.6 and 15.7 and continued north of the road which extended from a point south of
	Vogelsang to Gross Doelln. The Vietmannsdorf-Gross Doelln road was crossed about 165 meters south of the intersection of the lane between forest districts 193 and
	161 and to Vietmannsdorf-Gross Doelln road. About 250 meters west of this road the
	track made a curve to the northeast before entering the airfield area proper.2
10	. The logged-off area on which the airfield was being built began at a point 372
	meters north of the intersection of the lane between forest districts 193 and 161 and the Vietmannsdorf-Gross Doelln road. Another 165 meters north of this point,
	source observed the light masts south of the area where the runway was probably
	to be built. A further 99 meters north of this point there was another row of light masts. The distance from this northern row of light masts as far as the
	northern boundary of the logged off area was 242 meters. The lane which crossed the
	Vietmannsdorf-Gross Doelln road in forest district 218 was 264 meters distant from the northern boundary from the logged off area. Source learned from a surveying
	engineer employed at the hirfield that the runway scheduled to be built at the
	field was to measure 3,750x80 meters and to be provided with a concrete layer
X -	· ·
11	In mid-January, the two Soviet engineer units which had been employed for construction work at the field moved to some other location, according to a Soviet
	soldier about 70 km from Templin. The engineer unit commanded by Captain
	Bogush (fnu) had been stationed in Gollin, the unit commanded by Major Cytsoia in Grossvacter.
	SECRETA 25X1
	201

		Approved For Release 2002/07/15 : CIA-RDP80-00810A000900520009-6 25X1A
		25X1
	12.	Construction staff W 101 was headed by Colonel Kirck (fmu). One Aleksei was also assigned to this staff, which was quartered in single-story temporary buildings. One of these buildings, in which the construction records were said to be kept, was located near the Vietnamsdorf-Gross Doelln road.
	13.	According to a construction foreman concreting work at the field was to be started on 20 February. Work on eight multi-story buildings apparently accomodations had been started.
25X1A	1. [Comments Colonel Kirik, also referred to as Kirk, was previously known to be the chief of the Soviet construction stuff supervising construction work at Schorffielde airfield. Aleksel was reported for the first time. The names of commending officers of the engineer units previously employed at the field were reported for the first time.
25X1A 25X1	2.	Commente. These data clarify the route of the spur track leading to the airfield. See sheet 2946/47.
25X1A 25X1A	3.	Forments It was previously reported that shipments of construction materials to the airfield would be increased in February 25X1A The present report indicates that construction work at the riem is being accelerated.
25X1A	L ě	Comment. The data on the location of the runway and the boundaries of the logged-off area are believed to be correct. Information received on the measurements of the runway is contradictory. However, it is believed that the data furnished by source of the present report are correct. The statement that the runway will be provided with a concrete cover 50 cm thick indicates that the field might be used by heavy aircraft. Efforts have been initiated to determine the eastern end of the runway.
5 * *		
	•	

25X1

SECRET